

| | |
|---|---|
|  | BY-007 REPLACE: VW 032905106, 032905106B BOSCH 0 221 603 010 UF-277 |
|  | BY-014 REPLACE: VW 06A 905 097, 06A 905 104 UF-484 |
|  | BY-096 REPLACE: VW 07K905715F UF-575 |
|  | BY-127 REPLACE: AUDI/VW/SEAT 867905104, 867905104A, 867905352 UF364 |
|  | BY-128 REPLACE: VW/SEAT 022905100N/K/A/G/D UF-404 |
|  | BY-129 REPLACE: VW/Seat 022905100S/B/E/H/P/L UF-531 |
|  | BY-129L REPLACE: VW/Seat 022905100S/B/E/H/P/L UF-531 |
|  | BY-130 REPLACE: VW/Audi 06B905115R/G/H/J/L/M/N, ,06A905115 UF-411 NOTE: BLACK TOP |

| | |
|---|--|
|  | BY-131 REPLACE: VW/Audi 06C905115L/F UF-483 NOTE: RED TOP |
|  | BY-132 REPLACE: VW/Audi 06A905115D UF-411 NOTE: BLACK TOP |
|  | BY-133 REPLACE: VW/Audi 06C905115M UF-483 NOTE: RED TOP |
|  | BY-134 REPLACE: VW 06B905115E/B, 06B905115 UF-274 |
|  | BY-135 REPLACE: Audi 077905115Q/E/H/F/K UF-418 NOTE: RED TOP |
|  | BY-136 REPLACE: VW 022905100,022905100J/F/C UF-514 |
|  | BY-137 REPLACE: VW/Audi 078905104,88921391 UF-256 |

| | |
|---|---|
|  | BY-149 REPLACE: VW 021905106C UF-338 |
|  | BY-150 REPLACE: VW 021905106A, 021905106 UF-163 |
|  | BY-152 REPLACE: VW/AUDI 047905104A LUCAS DMB860 |
|  | BY-153 REPLACE: VW/AUDI 04C905110H,04C905110B/D/F/J 04E905110,04E905110A/B/C/D/E/F/H/K/L/M UF-718 |
|  | BY-155 REPLACE: VW 867905104,867905105A/B,357905104,547905104 BOSCH 0221601006,0221601007 UF-96 |
|  | BY-236 REPLACE: VW 036905100A/B/C/D,036905715A/C/E BOSCH 0986221023 UF-691 |
|  | BY-244 REPLACE: VW 06E905115E/D UF-529 |

| | |
|---|--|
|  | BY-257 REPLACE: VW 078905101A UF-376 |
|  | BY-271 REPLACE: VW 058905105,058905101 UF-290 |
|  | BY-284 REPLACE: VW 034905101 UF-275 |
|  | BY-298 REPLACE: VW 07C905115H UF-542 |
|  | BY-304 REPLACE: VW 06J905110D/E/F/G UF-716 |
|  | BY-305 REPLACE: VW 077905115G UF-521 |
|  | BY-308 REPLACE: VW 06H905115B UF-623 |